

Care Labels



	Normal (No Bar Underneath Image) Machine Washable Normal Cycle
	Permanent Press (Single Bar) Machine Washable Medium Cycle Mild Treatment
	Delicate/Gentle (Double Bar) Machine Washable Delicate Cycle Very Mild Treatment
	Hand Wash Only Do Not Machine Wash Handle With Care
	Do Not Wash Not Suitable For Washing
	Do Not Wring
	Do Not Bleach Use Only Bleach-Free Detergent
	Any Bleach Allowed Chlorine And Oxygen Bleach
	Non-Chlorine Bleach Only Oxygen Bleach When Needed
	Dry Flat Recommended For Garments Which Are Easily Distorted By Vertical Drying
	Hang/Line Dry For Garments Not Distorted By Vertical Drying Or Where Tumble Drying Is Not Recommended
	Drip Dry Recommended For Garments Which Will Withstand Distortion And Are Generally Synthetic In Nature

	Tumble Dry May Be Tumble Dried
	Tumble Dry Low Low Heat Setting
	Tumble Dry Medium Medium Heat Setting
	Tumble Dry High High Heat Setting
	Do Not Tumble Dry
	May Be Dry Cleaned
	May Be Dry Cleaned (This Letter Indicates The Process Required)
	Do Not Dry Clean Do Not Dry Clean Or Remove Stains With Solvents
	Cool Iron (One Dot) Maximum Sole-Plate Temperature Of 230°F, Steam-Ironing May Be A Risk
	Warm Iron (Two Dots) Maximum Sole-Plate Temperature Of 300°F
	Warm Iron (Two Dots) Maximum Sole-Plate Temperature Of 300°F
	Do Not Iron Steaming And Steam Treatments Are Not Allowed